



Left Bank Canals Area Water Board, Badin
Phulleli Canal Division, Badin
Camp Office @ Left Bank Barrage Colony, Hyderabad
Phone No.022-9210343
Website: www.sida.org.pk



No. TC/G-55/ 244

of 2019, Badin, Dated:

30/01/2019

REQUEST FOR QUOTATIONS

REPAIR OF DIRECTOR BUNGALOW LBOD COLONY BADIN.

The Government of Sindh has received a credit from the International Development Association (IDA) to implement the Sindh Water Sector Improvement Project Phase-I. These funds will be utilized for rehabilitation of the Main Canals, Branch Canals and Distributaries/ Minors and their structures, capacity development of institutions involved in implementation of the project.

Executive Engineer, Phulleli Canal Division Badin of Left Bank Canals Area Water Board Badin invites sealed quotations for the “**REHABILITATION WORKS FOR THE BUNGALOW OF DIRECTOR LBCAWB AT LBOD COLONY BADIN**” from the reputed sales tax and income tax registered Firms / Companies / Contractors having previous experience of above work may quote their competitive prices with inclusive of all Government applicable taxes, duties on or before 15-02-2019.

The received quotations shall be evaluated as per ‘shopping’ method under World Bank’s Procurement Guidelines. The acceptable terms & conditions of the lowest responsive quotation shall be incorporated in the Work Order. Conditional quotation will not be acceptable.


The work is required to complete within Sixty (60) days after issuance of work order. The quotation with complete details from the Firms / Companies / Contractors may be addressed to the Executive Engineer, Phulleli Canal Division Badin of Left Bank Canals Area Water Board Badin and submitted to the address given on the office letter pad.

The complete BOQ is attached as Annexure-‘A’ to this RFQ.


Executive Engineer
Phulleli Canal Division
Badin


Copy forwarded with complements for favor of information to the:

- Managing Director, Sindh Irrigation & Drainage Authority (SIDA), Hyderabad.
- Project Director WSIP-I SIDA Hyderabad.
- Director, Left Bank Canals Area Water Board, Badin
- Assistant Executive Engineer, Badin Sub Division, Badin.
- IT Specialist SIDA for hoisting on SIDA website.
- Copy for Notice Board.


Executive Engineer
Phulleli Canal Division
Badin

BOQ**Rehabilitation works for the Bungalow of Director, LBCAWB at LBOD Colony Badin**

S.No:	Description	Unit	Qty	Rate	Amount
1	Dismantling brick work in lime or cement mortar. (S.I No.13 Page-10)	%Cft	6402		
2	Dismantling Cement Concrete Reinforcement separating reinforcement from concrete cleaning and strengthening the same. (S.I No. 20 Page-10)	%Cft	1473		
3	Pacca Brick Work in Foundation and plinth in Cement sand mortar Ratio 1:5.	% Cft	3677		
4	R.C.C work including all labour and material except the cost of steel reinforcement and its labour for bending and blinding which will be paid separately. This rate also includes all kinds of forms, mould, lifting, shuttering, curing, rendering and finishing the exposed surface (including screening and washing of shingle (a) R.C.C work in roof slab, beams, column, rafts, lintels and other structural members laid in situ or precast laid in position. Complete in all respects (i) Ratio 1:2:4 (S.I.No. 6(a) Page-16)	P.Cft	1473		
5	Fabrication of mild steel reinforcement for cement concrete including cutting, bending, laying in position, making joints and fastening including cost of binding wire (also includes removal of rust from bars. (S.I.No. 8 (a) Page-13)	P.Cwt	65.74		
6	Scraping (b) Ordinary Distemper, Oil Bound Distemper or Paints on wall (S.I No.54 (b) Page-13)	% Sft	2054		
7	Cement plaster 1:2 upto 12ft height ½ " thick. (S.I.No. 09 (b)/Page-51)	% Sft	11854		
8	First Class deodar wood , fixed in position including chowkats holds fasts hinges, iron tower bolts, choks cleats, handles and cords with hooks etc (wrought, joinery in doors and windows etc (b) 1 ¾ " thick. (S.I No.7 (b) Page-57)	% Cft	639		
Total in Pak Rs.					


 Executive Engineer
 Phulleli Canal Division
 Badin